Approved For Release 2003/12/11: CIA-RDP69B00404-000100260019-7

		25X1
Copy 5 of	11	
14 November	1967	

MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6734

1. Following is a summary of Mission Number BX6734. A general critique will not be held due to a special investigation of hostile activity encountered on this mission. Formal briefings will be held on investigations findings.

2. Mission Data:

- a. Mission Number: BX6734
- b. Date Flown: 30 October 1967
- c. Area of Operation: North Vietnam
- d. Mission Successful
- e. Pilot's Name:
- f. Aircraft Number: 129
- g. Primary or Spare Flown: Primary
- h. Takeoff Time Planned: 0220Z

Actual: 02197.

i. Landing Time - Planned: 0607Z

Actual: 0603Z

j. Time Enroute - Planned: 3+47

Actual: 3+44

- k. Departure Base: Kadena Air Base
- 1. Landing Base: Kadena Air Base
- m. Equipment:

25X1

25X1

25X1

(1) Primary: Type I,

(2) Spare: Same as primary.

25X1

GROUP 1
Excluded from automatic
downgreding and
declassification

Approved For Release 2003/12/11 : CIA-RDP69B00404R000100260019-7

TOP SECRET

25X1

CIA-RDP69B00404R000100260019-7

Approved For Release 2003/12/11:

	Approved Formelease 2003/12/11 : CIA-RDP69B004 R0000100260019-7
	b. Quality of Take: Satisfactory.
	(1) Resolution: Good. (2) Camera Operation: Normal.
	d. Significant Findings: SAMs were launched at
. [mission aircraft from the general Hanoi area while aircraft was on its second pass. There is no clear evidence that a missile firing was made against the aircraft on the first pass. If a firing occurred, it most likely was directed against another type aircraft.
	f. Take Movement:
(1	
	6. Materiel: a. Aircraft General: Satisfactory.
1	(1) Comments: due to a broken wire. Autopilot pitch trim did not operate properly. Pitch gyro was changed and autopilot operation was normal on next flight.
	b. Aircraft Systems: Satisfactory.
•	

TOP SECRET

25X1

Page 4

25X1

7. Communications: Satisfactory.

- a. Message Traffic: Satisfactory.
- 8. Significant Actions Taken:

Special investigation now in progress to determine OXCART SAM vulnerability. This will be subject of separate report.

9. Outstanding Actions Required:

Complete SAM vulnerability study and submit report as soon as practical (Office of Special Activities, Office of ELINT and Office of Scientific Intelligence).

25X1

WILLIAM E. SHELTON
Colonel, USAF
Deputy for Operations, OSA

25X1

OXC/O/OSA

Distribution:

#1 - D/SA

#2 - D/O/OSA

#3 - D/M/OSA

#4 - D/R&D/OSA

#5 - OXC/O/OSA

#6 - Intel/O/OSA

#7 - Wea/O/OSA

#8 - Commo/O/OSA

#9 - ADP/O/OSA

#10 - RB/OSA

#11 - CHRONO

25X1

25X1

Approved For Release 2003/12/14 CEIA-RDP69B00404R000100260019-7